

BENZIE-LEELANAU DISTRICT HEALTH DEPARTMENT

Foodservice Establishment Inspection Report

Establishment Information			
Facility Name Lake Ann Corner Llc/Corner Cone	Facility Type Fixed Establishment-365	State License Number SFE1010216164	Facility Telephone # 231 276-1236
Facility Address 6515-B First St , Lake Ann , MI , 49650			
Inspection Information			
Inspection Type Follow-up		Inspection Date 06/17/2022	

This facility was inspected to determine the level of compliance with Food Law of 2000 Act No. 92. Violations cited in this report shall be corrected with the time frames specified below, but within a period not to exceed 10 calendar days for priority or priority foundation items (8-405.11) or 90 days for core items (8-406.11). Failure to comply with this notice may result in license suspension and/or other legal action. You have the right to appeal any violation listed.

Observed Priority Violations
Total # 0
Repeated # 0
Observed Priority Foundation Violations
Total # 0
Repeated # 0
Observed Core Violations
Total # 0
Repeated # 0

Law and code excerpts in report are for information only and not as the basis for legal or judicial determinations. Always verify them against the most recent available copy of the law and code.

Corrected Hazards
The following hazard(s) have been corrected since the last inspection. Total # 2 5-202.13 - BACKFLOW PREVENTION, AIR GAP This is a priority item Observation: Observed the spray arm at the single prep sink unable to automatically hang above the flood level rim. The noted spray arm could be left inside of the prep sink causing an improper air gap. Corrective Action(s): Provide an air gap between the spray arm and the flood level rim of the prep sink. Correct By: 05-Jun-2022 Action Taken: Observed the spary arm removed from the noted sink. Code citation: An air gap between the water supply inlet and the flood level rim of the plumbing fixture, equipment, or nonfood equipment shall be at least twice the diameter of the water supply inlet and may not be less than 25 mm (1 inch). 5-205.15 (B) - SYSTEM MAINTAINED IN GOOD REPAIR (REPAIRED) This is a core item Observation: Observed a slight leak at the 3 compartment sink below the wash basin drain line. Observed water dripping into a container. Corrective Action(s): Repair the noted drain line to prevent it from leaking. Correct By: 26-Aug-2022 Action Taken: Observed the drain line no longer leaking. Code citation: The PLUMBING SYSTEM shall be: (B) Maintained in good repair.

Comments
No follow up inspection required. Observed 5-202.13 (Air gap) in compliance at time of follow up inspection. Questions? Call Nick at 231-256-0216 or ndow@bldhd.org. Person in charge signature was not captured due to BLDHD COVID-19 inspection protocols. Inspection report was emailed to store@corner-cone.com.

Person in Charge

Chris

Sanitarian

Nick Dow